

Release Note 20100324_Netcomm_N3G007W_R705a5_0324 FW

Information

- Product Code: N3G007W
- Firmware Version: R705a5_0324
- Filename: 20100324_Netcomm_N3G007W_R705a5_0324.BIN
20100324_Netcomm_N3G007W_R705a5_0324.exe
- Date: 24 March, 2010

Firmware Upgrade Instructions

Please ensure that your 3G USB Modem is not attached to NetComm Router during the upgrade process as this may damage the router and render it as unusable.

For user using the exe file to upgrade the firmware:

1. Connect the computer to any LAN socket on the N3G007W.
2. Double click the Firmware_version.exe
3. Type in System Password on the password field.
4. Click **Upgrade** to proceed. It will take a few minutes to proceed upgrading till the status bar reaches 100%.
5. Do not turn off the modem during the upgrade.
6. N3G007W will reboot itself after upgrade.

For user using the bin file to upgrade the firmware:

1. Connect the computer to any LAN socket on the N3G007W.
2. Open the web browser (IE, Mozilla firefox, etc) on the computer, type in <http://192.168.123.254> on the address bar, and then press **Enter**.
3. Type in System Password on the top then press **Login**
4. Click **Advanced Setup**, then click **TOOLBOX** on the top menu, select **Firmware Upgrade** in the left-hand side menu.
5. Press the **Browse** button and load the latest Firmware.
6. Click **Upgrade** to proceed. It will take a few minutes to proceed upgrading till the status bar reaches 100%.
7. Do not turn off the modem during the upgrade.
8. N3G007W will reboot itself after upgrade.

New Features

- Support a new 3G dongle Sierra Wireless USB 308 Bigpond
- Support a new 3G dongle Huawei E1756

Fixes:

- Fixes the UI issue

Release Note 20100206_Netcomm_N3G007W_R705a5 FW

Information

- Product Code: N3G007W
- Firmware Version: R705a5
- Filename: 20100206_Netcomm_N3G007W_R705a5.BIN
20100206_Netcomm_N3G007W_R705a5.exe
- Date: 06 Feb, 2010

New Features

- Support a new 3G dongle Sierra Wireless USB 308
- Support a new 3G dongle ZTE MF 633+ BP

Fixes:

- Fix the signal strength could not show correctly on the WEB GUI for the Sierra Wireless 880U.
- USB-306 firmware 2.0.11.5 supported (fixed)

Known Issues

Release Note 20100108_Netcomm_N3G007W_R705a1 FW

Information

- Product Code: N3G007W
- Firmware Version: R705a1
- Filename: 20100108_Netcomm_N3G007W_R705a1.BIN
20100108_Netcomm_N3G007W_R705a1.exe
- Date: 08 January, 2010

New Features

- Support a new 3G dongle Huawei K3765

Fixes:

- Improved Sierra Wireless USB 306 throughput speed by 50%.

Known Issues

- Incorrect display strength on the WEB GUI for the Sierra Wireless 880U.

Release Note 20091012_Netcomm_N3G007W_R704b2 FW

Information

- Product Code: N3G007W
- Firmware Version: R704b2
- Filename: 20091012_Netcomm_N3G007W_R704b2.BIN
20091012_Netcomm_N3G007W_R704b2.exe
- Date: 12 Oct, 2009

New Features

- Support a new 3G dongle ZTE MF633 +
- Support a new 3G dongle ZTE 3565-Z
- Support a new 3G dongle ZTE MF 668+

Fixes:

- Wizard APN updated.

Known Issues

- Sierra Wireless USB 306 with low throughput speed.
- Incorrect display strength on the WEB GUI for the Sierra Wireless 880U.

Release Note 20090806_Netcomm_N3G007W_R704a0_0806 FW

Information

- Product Code: N3G007W
- Firmware Version: R704a0_0806
- Filename: 20090806_Netcomm_N3G007W_R704a0_0806.BIN
20090806_Netcomm_N3G007W_R704a0_0806.exe
- Date: 06 August, 2009

New Features

- Update the wizard page

Fixes:

Known Issues

Release Note 20090716_Netcomm_N3G007W_R704a0_0716 FW

Information

- Product Code: N3G007W
- Firmware Version: R704a0_0716
- Filename: 20090716_Netcomm_N3G007W_R704a0_0716.BIN
20090716_Netcomm_N3G007W_R704a0_0716.exe
- Date: 16 July, 2009

New Features

- Update the latest APN on the wizard page

Fixes:

- Fix time scheduling with packet filter issue.

Known Issues

Release Note 20090514_Netcomm_N3G007W_R703a1_0514 FW

Information

- Product Code: N3G007W
- Firmware Version: R703a1_0514
- Filename: 20090514_Netcomm_N3G007W_R703a1_0514.BIN
20090514_Netcomm_N3G007W_R703a1_0514.exe
- Date: 14 May, 2009

New Features

Fixes:

- Improved and modified the wizard page.

Known Issues

Release Note 20090325_Netcomm_N3G007W_R703a1 FW

Information

- Product Code: N3G007W
- Firmware Version: R703a1
- Filename: 20090325_Netcomm_N3G007W_R703a1.BIN
- Date: 25 March, 2009

New Features

- Compatible with Sierra Wireless USB306 (21Mbps Dongle)

Fixes:

Known Issues

Release Note 20090218_Netcomm_N3G007W_R702a3 Beta FW

Information

- Product Code: N3G007W
- Firmware Version: R702a3 beta
- Filename: 20090218_Netcomm_N3G007W_R702a3_beta.BIN
- Date: 18 February, 2009

New Features

- Compatible with ZTE MF 627

Fixes:

Known Issues

Release Note 20090206_Netcomm_N3G007W_R702a2 beta FW

Information

- Product Code: N3G007W
- Firmware Version: R702a2 beta
- Filename: 20090206_Netcomm_N3G007W_R702a2_beta.BIN
- Date: 6 February, 2009

New Features

- Compatible with Huawei E180
- Compatible with ZTE MF 636 BP

Fixes:

- Update the latest APN on the wizard page
- Fixed the authorization message appear every time the device has been configured
- Fixed an issue every time the user log in, it will direct to the wizard page rather the log in page.

Known Issues

Release Note 20081125_Netcomm_N3G007W_R701a3

Information

- Product Code: N3G007W
- Firmware Version: R701a3
- Filename: 20081125_Netcomm_N3G007W_R701a3.bin
- Date: 25 Nov, 2008

New Features

Added the compatibility to following USB 3G routers:

ISP: Telstra

- ZTE MF 626
- ZTE MF 636 (Non BP)
- Sierra Wireless 597U
- Sierra AC885

Known Issues

Release Note 20081107_Netcomm_N3G007W_R701a2

Information

- Product Code: N3G007W
- Firmware Version: R701a2
- Filename: 20081107_Netcomm_N3G007W_R701a2.bin
- Date: 07 Nov, 2008

New Features

Added the compatibility to following USB 3G routers:

- Sierra Wireless' Compass 885

ISP: Three

- Huawei 169 (or K3715 as modeled by Vodafone)
- Huawei 160

Known Issues

Release Note 20080929_Netcomm_N3G007W_R701a1

Information

- Product Code: N3G007W
- Firmware Version: R701a1
- Filename: 20081003_Netcomm_N3G007W_R701a1
- Date: 29 Sept, 2008

New Features

- Support LightSpeed HSUPA-180C,HSUPA-380P
- Support Bandluxe C120(with new firmware)
- Fix RIPv2 issue.Router will only send RIPv2 packet when set in RIPv2 option
- PPTP/L2TP MSS value Fix to 1420

Fixes:

- Fix RIPv2 issue. Router will only send RIPv2 packet when set in RIPv2 option
- PPTP/L2TP MSS value Fix to 1420

Known Issues