

ADSL2+ AC1200 WiFi Gigabit Modem Router with Voice

NB16WV-03



Firmware Release Notes

Copyright

Copyright© 2015 NetComm Wireless Limited. All rights reserved.

The information contained herein is proprietary to NetComm Wireless. No part of this document may be translated, transcribed, reproduced, in any form, or by any means without prior written consent of NetComm Wireless.



Please note: This document is subject to change without notice.

DOCUMENT VERSION	DATE
1.0 Initial document release	23 February 2015


Release information

ITEM	DETAILS
Product Code	NB16WV-03
Product Name	ADSL2+ AC1200 WiFi Gigabit Modem Router With Voice
Firmware Version	NCRG0.1009_01231520
Beta/Official	Official
Firmware file name	2015.01.23_NetComm_NB16WV-03_NCRG0.1009_01231520.bin
Firmware file size	10.4 MB
MD5 Sum	E7C3479895CEACAA539F66AE71C5DCEB
Date	23 February 2015


Firmware upgrade instructions

To upgrade the firmware of the NB16WV-03 router:

1. Connect the power adapter and press the Power button at the back of NB16WV-03 to turn on the NB16WV-03.
2. Allow 60 – 90 seconds for the NB16WV-03 to power up.
3. Use the included Ethernet cable to connect your computer to any yellow Ethernet port on the NB16WV-03.
4. Open a web browser (Internet Explorer, Firefox, etc) on the computer, type <http://192.168.20.1> in the address bar, then press **Enter**.
5. Type in the System Password (the default one is *admin* for both Username and Password) then press **Login**.
6. Click **Toolbox** and then click **Firmware Upgrade** on the top menu.



7. Press the **Browse** button and load the firmware (2015.01.23_NetComm_NB16WV-03_NCRG0.1009_01231520.bin).
8. Click **Upgrade** to proceed. It will take a few minutes to proceed upgrading until the router reboots itself.
9. Once the upgrade is done, you are taken to the Login page. Type in the System Password (the default one is *admin* for both Username and Password) then press **Login**.
10. Click **Toolbox** and then click **Firmware Upgrade** on the top menu.








11. Ensure the current firmware version is **NCRG0.1009_01231520**.



Release history

NCRG0.1009_01231520

Changes/New features

-  Added support for IPv6 packet filtering.
-  Added support for Classful Network Addressing.
-  Updated TR-069 software code.
-  Updated Status page information for VoIP.
-  Support DNS on TCP

Bug fixes

-  Fixed TR-069 functionality.
-  Fixed an issue were users are allowed default password for “Remote Admin”.

Known issues

-  None.

NCRG0.1008_11271702 – Initial production release


New Features

-  None

Bug Fixes

-  None

Known Issue

-  None