

Information

- Product Code: NTC-990
- Product Description: 900MHz HSPA Cellular Router
- Router Firmware Version : V1.57.8
- Phone Module Firmware Version: K1_0_2_18A
- Beta/Official: Official
- Filename: upgrade-1.57.1-1.57.8.cramfs
- File size: 1.15MB
- Date: 16 Oct 2009

Upgrade Instructions

Please refer to file named: [Oct2009 NTC-990 FW1.57.1 -1.57.8 firmware upgrade instruction.pdf](#) for firmware upgrade instruction.

Warning:

The firmware upgrade instruction is applicable only to NTC-990 running router firmware V1.57.1. If you presently have an Application Software version other than V1.57.8 you will need contact NetComm technical support to obtain an upgrade pack at either:

Phone: +61 (02) 9424-2059
Email: TechnicalSupport@netcomm.com.au

New Features

Bug Fixes / Modifications

1.57.8

- 1 Fixed 3G PPP connection issue with some carriers (Internode 3G and Dodo)
- 2 Fixed incorrect HELP button content and hyperlinks in the status page

1.57.7

1. Fixed NTC-990 GUI banner description

1.57.5

- 1 DHCP Server field in GUI filling with unexpected string after RESTORE FACTORY DEFAULTS caused DHCP stops working.
- 2 Fixed GUI "tableHeader.gif" display problem if the screen resolution is set to more than 1920 pixel.
- 3 Both links can be used for phone module firmware and boot loader upgrade.
<http://192.168.1.50/linkFiles/FlashUpload.html> or
<http://192.168.1.50/FlashUpload.html>
- 4 Fixed UI sub-menu 'VPN' link to an incorrect URL, cannot go to "VPN" page from main menu. (only applicable to the NTC models loaded with VPN patch)
- 5 ATI command returns incorrect router description.
- 6 Fixed intermittent long response time for some AT command

1.57.1

1. Fixed CNS watch-dog acts too quickly, during high traffic operation, the router may reset.
2. Fixed incorrect SNMP ppp connection status
3. Fixed SNMP not setup when configuration exports, the SNMP does not work until the user applies SNMP settings when the configuration exported

Known Issue