Information

- ➢ Product Code: Dynalink RTA Series ADSL2+ Modem Router (RTA1025W/RTA1030W/RTA1335)
- ➢ Firmware Version: 3.64y
- ➢ Filename:
  - RTA1025:
    - cfe-rta1025wnz-v364y_a2pb025c
    - cfe-rta1025wnz_tc-v364y_a2pb025c (Telstra Clear)
  - RTA1030W:
    - cfe-rta1030wnz-v364y_a2pb025c
    - cfe-rta1030wnz_tc-v364y_a2pb025c(Telstra Clear)
  - RTA1335:
    - cfe-rta1335nz-v364y_a2pb025c
    - cfe-rta1335nz_tc-v364y_a2pb025c(Telstra Clear)
- ➢ Date: 17, April, 2009

## Bug Fix

- ➢ Fixed Adam Australia PPP issue.

Upgrade Instructions

Please follow these steps to upgrade your RTA Series ADSL2+ Modem Router (RTA1025W/RTA1030W/RTA1335) firmware:

1. Connect to your RTA1025W/RTA1030W/RTA1335 using an Ethernet cable. It is advised that you do not perform the upgrade wirelessly.
2. Open a web browser (e.g. Internet Explorer) and enter http://192.168.1.1 into the Address bar:

3. Click on Update Firmware:

4. Click Browse and choose the corresponding RTA series modem router's firmware binary file that you downloaded from Dynalink's website and click Update Firmware:

5. The following page will display if the firmware has been accepted:

6. Wait for 2 minutes as your router saves the firmware and reboots.

   NOTE: DO NOT DISCONNECT YOUR PC FROM THE MODEM or POWER THE RTA1025W/RTA1030W/RTA1335 OFF!

7. When the power light changes from Red to Green, the firmware update is complete.