V220 Release Note

Information

- ➢ Product Code: V220 VoIP ATA

- ➢ Firmware Version: CA2S_90306_NET_02_90721

- ➢ Filename: V220_CA2S_90306_NET_02_90721.rom

- ➢ Date: 23th July 2009

Fixes and Feature

1. Added DHCP 66 feature;
2. Added TFTP auto configuration update feature;

Upgrade Instructions

1. Connect your LAN port of the V220 to your PC.
2. Run any Web browser, like Microsoft Internet Explorer. Go to *"http://*192.168.22.1"to access the V220 home page.
3. Enter the username / password as admin/admin as default.
4. Click "Firmware Update" and "browse" to locate the latest Firmware and press "update".
5. Wait for 2 minutes for the device to reboot itself.

Caution: After upgraded to CA2S_90306_NET_02_90721, it would cause V220 ATA CRASH if trying downgrade your V220 to any older firmware version!