

## Release Note NP800n-NP801n 1.2.1 Firmware

### Information

- Product Code: NP800n/NP801n
- Firmware Version: NP800n/NP801n-1.2.1
- File Name:  
NP800n-NP801n-APPS-V1-2-1-4.dlf  
NP800n-NP801n-KNL-V1-2-1-7.dlf
- Date: 22 January 2010

### Upgrade Instructions

1. With the NP800n or NP801n connected to your PC, suppose that server is in DHCP mode.
2. Check the NP800n/NP801n's IP address
3. Run any Web browser, like Microsoft Internet Explorer. Go to "[http:// NP800n or NP801n's IP address](#)" to access the NP800n/NP801n home page.
4. Click "Tools" then "Firmware".
5. Click "browser" to locate the latest **Firmware** and press apply.
6. First upgrade in this order
  - a.) NP800n-NP801n-APPS-V1-2-1-4.dlf
  - b.) NP800n-NP801n-KNL-V1-2-1-7.dlf

### New Features

- N/A

### Fixes:

- Solve input error of iPhone's MAC address in Web GUI.
- Fixed the Safari 4 issue.
- WEB GUI updtcs
- Model name change : Velocity Series

## Release Note NP800n-NP801n 1.2.0 Firmware

### Information

- Product Code: NP800n/NP801n
- Firmware Version: NP800n/NP801n-1.2.0
- File Name: NP800n-NP801n-APPS-V1-2-0-56.dlf  
NP800n-NP801n-KNL-V1-2-0-55.dlf
- Date: 3 August 2009

### New Features

- Support release WPS Status function.
- Support the specific port can set TCP or UDP in Priority Queue page.
- Hardware reset while sysconfd is down.

### Fixes:

- Fixed the repeater and WDS issues.
- Fixed Setup Wizard issue: It will be fail to next step in the Operation Mode's selection of Setup Wizard WEB page.
- Fixed URL Filter issue: Enter a rule with string "http", the DUT will hang up.
- Fixed the LAN IP Addressing issue: IP Subnet Mask can be 0.0.0.0 with no warning message in System->LAN WEB page and will make DUT freeze.
- Fixed WEB content: Internet > PPPOE change to Internet > PPPoE.
- Fixed the Static IP in WAN setting issue: IP Subnet Mask can set 0.0.0.0 in Internet ->Static IP WEB page.
- Fixed Spanning Tree UI issue: when Spanning Tree setting Enabled, it always show Disabled of System -> LAN WEB page in AP Repeater mode.
- Fixed when upgrade over size file will make DUT freeze.
- Fixed Port Mapping /Port Forwarding issue: one client in LAN site cannot access another through WAN port IP address.
- Fixed the Safari browser compatibility issue.
- Modify Bandwidth Allocation UI issue: for IE browser, if we press the "Reset" button, the form of Rate will be blank, then we set "Local IP range" and "Port range" and apply, it will be fail. And for Opera, Safari and Firefox browser, if we press the "Reset" button, the form of Rate will not to reset.
- Fixed WEB Content issue: 1. Set 63 ' as WPA2-AES key then apply. The webpage Wireless->Security and Wireless->WPS couldn't be opened. The only way is factory default DUT. Some other special ASCII keys, such as \ and ", can cause the same problem.
- Fixed Multi-SSID issue: upgrade Firmware to modify LAN/WLAN MAC address.
- Fixed PPTP SYN packet issue: 1. When DUT in PPTP-Static mode, DUT will send SYN packet to its "Gateway IP Address", not "Service IP Address". It should route packets through "Gateway IP Address" and destined to "Service IP Address". This issue doesn't happen in PPTP-DHCP mode.

- Change QoS setting will make the function abnormal.
- Fixed Daylight Saving display issue in IE browser.
- Fixed Two PCs in LAN side run Chariot with High Performance script will make the DUT's WAN down and then up issue.

#### Change

- Modify UI: remove DDNS, Remote management, WAN Monitor, power saving and schedule function in AP Repeater mode.
- Remove Policy page in Wireless setting.

## Release Note NP800n-NP801n 1.1.13 Firmware

### Information

- Product Code: NP800n/NP801n
- Firmware Version: NP800n/NP801n-1.1.13
- File Name: NP800n-NP801n-APPS-V1-1-13-45.dlf  
NP800n-NP801n-APPS-V1-1-13-91.dlf
- Date: 06Oct2008

### New Features

N/A

### Fixes:

- Fix the date code makes reboot and ping time out issue

### Known Issues

N/A

## Release Note NP800n-NP801n 1.1.12 Firmware

### Information

- Product Code: NP800n/NP801n
- Firmware Version: NP800n/NP801n-1.1.12
- File Name: NP800n-NP801n-APPS-V1-1-12-43.dlf
- Date: 10Step2008

### New Features

N/A

### Fixes:

N/A

### Changes

- Change default Wireless Key from 1a2b3c4d5e to a12b3c4d5e

### Known Issues

N/A

## Release Note NP800n-NP801n 1.1.11 Firmware

### Information

- Product Code: NP800n/NP801n
- Firmware Version: NP800n/NP801n-1.1.11
- File Name: NP800n-NP801n-APPS-V1-1-11-43.dlf
- Date: 08Step2008

### New Features

N/A

### Fixes:

- Fixed firewall is disable Dos is still enabled issue.
- Fixed Remote Control when the port from 8080 to 80, the router will be frozen issue.
- Fixed NTP not works properly.
- Fixed G Mode throughput Fail issue

### Changes

N/A

### Known Issues

N/A

## Release Note NP800n-NP801n 1.1.10 Firmware

### Information

- Product Code: NP800n/NP801n
- Firmware Version: NP800n/NP801n-1.1.10
- File Name: NP800n-NP801n-APPS-V1-1-10-42.dlf
- Date: 04Step2008

### New Features

N/A

### Fixes:

- Fixed Remote Control issue.
- Filter Multicast IP Address in IP field.
- Fixed check mechanism of upgrade firmware / configuration file

### Changes

N/A

### Known Issues

N/A