

Information

- Product Code: Dynamalink RTA Series ADSL2+ Modem Router (RTA1025W/RTA1030W/RTA1335/RTA1046VW)
- Firmware Version: 3.64y
- Filename:
 - RTA1025: cfe-rta1025wau-v364y_a2pb025c
 - RTA1030W: cfe-rta1030wau-v364y_a2pb025c
 - RTA1335: cfe-rta1335au-v364y_a2pb025c
 - RTA1046VW: cfe-rta1046vw_sip_au-v364y_a2pb025c
- Date: 17, April, 2009

Bug Fix

- Fixed Adam PPP issue.

Upgrade Instructions


Please follow these steps to upgrade your RTA Series ADSL2+ Modem Router (RTA1025W/RTA1030W/RTA1335/RTA1046VW) firmware:

1. Connect to your RTA1025W/RTA1030W/RTA1335/RTA1046VW using an Ethernet cable. It is advised that you do not perform the upgrade wirelessly.
2. Open a web browser (e.g. Internet Explorer) and enter <http://192.168.1.1> into the Address bar:



3. Click on Update Firmware:

3. Click on Update Firmware:



4. Click Browse and choose the corresponding NB6 series modem router's firmware binary file that you downloaded from Dynamalink's website and click Update Firmware:

- The following page will display if the firmware has been accepted:

- Wait for 2 minutes as your router saves the firmware and reboots.

NOTE: DO NOT DISCONNECT YOUR PC FROM THE MODEM or POWER THE RTA1025W/RTA1030W/RTA1335/RTA1046VW OFF!

- When the power light changes from Red to Green, the firmware update is complete.