



NB8WVPN Firmware Upgrade Instructions

1. Connect the LAN port of the NB8WVPN to your PC with an Ethernet Cable. It is advised that you do not perform the upgrade wirelessly.
2. Open a web browser, such as Internet Explorer, and enter `http://192.168.1.1` in the address bar.



3. Enter "**admin**" for both username and password when prompted.



The screenshot shows the NetComm Wireless ADSL2+ Router web interface. The left-hand side menu is visible, with 'Update Firmware' highlighted in a red box. The main content area displays the breadcrumb 'Mangement > Setting > Update Firmware' and three steps for the update process. A 'Software File Name' field with a 'Browse...' button and an 'Update Software' button are also present.

NetComm[™]
Wireless ADSL2+ Router

Mangement > Setting > Update Firmware

Step 1: Obtain an updated software image file from your ISP.

Step 2: Enter the path to the image file location in the box below or click the "Browse" button to locate the image file.

Step 3: Click the "Update Software" button once to upload the new image file.

NOTE: The update process takes about 2 minutes to complete, and your DSL Router will reboot.

Software File Name:

Basic
Wireless
Management
Device Settings
Backup
Update
Restore Default
Update Firmware
SNMP
SNTP
Access Control
Save/Reboot
Advanced
Status

4. On the left-hand side menu, click **Management -> Device Settings -> Upgrade Firmware**.

5. Click the **"Browse"** button and choose the binary firmware file you downloaded and unzipped from the Netcomm website (e.g. A101-306NCM-C02_R07.bin) and click the **"Update Software"** button.

NetComm™
Wireless ADSL2+ Router

Basic
Wireless
Management
Device Settings
Backup
Update
Restore Default
Update Firmware
SNMP
SNTP
Access Control
Save/Reboot
Advanced
Status

Mangement > Setting > Update Firmware

Step 1: Obtain an updated software image file from your ISP.

Step 2: Enter the path to the image file location in the box below or click the "Browse" button to locate the image file.

Step 3: Click the "Update Software" button once to upload the new image file.

NOTE: The update process takes about 2 minutes to complete, and your DSL Router will reboot.

Software File Name:

6. Wait for about 3 minutes for NB8WVPN to complete the upgrade.
7. Reset the NB8WVPN to its factory default settings by selecting the **"Restore Default Settings"** button under **Management > Device Settings > Restore Default**.
8. Log in and reconfigure the router.