NB9WMAXXn Firmware Release Notes



Date of Created: 30/04/2010 Date of Latest Revision: 30/04/2010 Revision Level: 1

Release Version NB9WMAXXn-D111-S310NCM-C01_R07

Information

Product Code: NB9WMAXXn

> Hardware Version: 1.0

> Filename: NB9WMAXXn-D111-S310NCM-C01_R07.bin

> Date: 30th April 2010

Upgrade Instructions

- 1. Connect the LAN port of the NB9WMAXXn to your PC with an Ethernet Cable.
- 2. Open a web browser, (Such as Microsoft Internet Explorer). Go to http://192.168.1.1/ to access the NB9WMAXXn management console.
- 3. On the left-hand side menu, click on Management > Device Settings > Update Firmware;
- 4. On the right-hand side, click on the **Browse** button to search your local hard drive and locate the firmware to be used for update. Select the firmware file and press **Open.**
- 5. Click **Update Software** to proceed.
- 6. Wait for 2 minutes for the device to upgrade and reboot itself.

New Features / Fixes

- 1. Fixed the Remote Web Interface login security issue.
- 2. Fixed SIP Registration issue for TPG and linet.