

## Release Notes 20090217\_Netcomm\_NP3680W\_2.50

### Information

- Product Code: NP3680W
- Firmware Version: 2.50
- Utility Version: 2.50
- Filename: NP3680W\_v2.50.BIN
- Date: 17 February, 2009

### Upgrade Instructions

1. Connect the computer to the LAN socket on the NP3680W.
2. Assign a static IP address to your computer in the range of 192.168.1.x.
3. Open the web browser (Internet Explorer, Mozilla Firefox, etc) on the computer, type in <http://192.168.1.100> on the address bar, and then press **Enter**.
4. Click **Maintenance**, and then click **Upgrade Firmware**.
5. Click **Choose File** to browse your computer for the firmware file. Once you have located the correct file, click **Open**, and then click **Upload**.
6. It will take a few minutes to upgrade the firmware. Do not turn off the modem during the upgrade.
7. The NP3680W will reboot itself after upgrade.

### New Features

- New feature: Wireless - Support WPA 2 and AES.
- New feature: FTP - Support mget/mput commands.

### Fixes:

- Fix bug: For HP LaserJet 3500, print job will remain in queue after print out.
- Fix bug: FTP bug for the codepage of simple Chinese.

### Known Issues

## Release Notes 20081001\_Netcomm\_NP3680W\_2.36

### Information

- Product Code: NP3680W
- Firmware Version: 2.36
- Utility Version: 2.361
- Filename: NP3680W\_v2.36.BIN
- Date: 01 October, 2008

### Upgrade Instructions

1. Connect the computer to the LAN socket on the NP3680W.
2. Assign a static IP address to your computer in the range of 192.168.1.x.
3. Open the web browser (Internet Explorer, Mozilla Firefox, etc) on the computer, type in <http://192.168.1.100> on the address bar, and then press **Enter**.
4. Click **Maintenance**, and then click **Upgrade Firmware**.
5. Click **Choose File** to browse your computer for the firmware file. Once you have located the correct file, click **Open**, and then click **Upload**.
6. It will take a few minutes to upgrade the firmware. Do not turn off the modem during the upgrade.
7. The NP3680W will reboot itself after upgrade.

### New Features

### Fixes:

- Fix bug: For NTFS, file size cannot be larger than 4GB.
- Fix bug: Cannot upgrade firmware using Firefox/Safari.
- Fix bug: Wireless - cannot connect to access point if SSID is non-ASCII.
- Fix bug: NetUSB - cannot work if two same devices connected.
- Fix bug: SMB cannot work on XP 64 bit if security turned on.
- Fix bug: Firewall bug in XP 64 bit.
- Fix bug: Reload bus failed on Windows 2000.
- Performance Tuning: The READ operation of large file (NetUSB mode) is slow.

### Known Issues

## Release Notes 20080325\_Netcomm\_NP3680W\_2.33

### Information

- Product Code: NP3680W
- Firmware Version: 2.33
- Utility Version: 2.33
- Filename: NP3680W\_v2.33.BIN
- Date: 25 March, 2008

### Upgrade Instructions

1. Connect the computer to the LAN socket on the NP3680W.
2. Assign a static IP address to your computer in the range of 192.168.1.x.
3. Open the web browser (Internet Explorer, Mozilla Firefox, etc) on the computer, type in <http://192.168.1.100> on the address bar, and then press **Enter**.
4. Click **Maintenance**, and then click **Upgrade Firmware**.
5. Click **Choose File** to browse your computer for the firmware file. Once you have located the correct file, click **Open**, and then click **Upload**.
6. It will take a few minutes to upgrade the firmware. Do not turn off the modem during the upgrade.
7. The NP3680W will reboot itself after upgrade.

### New Features

- New feature: Supports Toshiba MFPs.

### Fixes:

- Fix bug: SMB protocol sometimes will run out of TCP/IP internal buffers.
- Fix bug: Cannot save file on Network Drive (SMB) using "Lotus SmartSuite" in Windows.
- Fix bug: Cannot see USB devices in Vista 64bit.

### Known Issues

## Release Notes 20080325\_Netcomm\_NP3680W\_2.33

### Information

- Product Code: NP3680W
- Firmware Version: 2.33
- Filename: NP3680W\_v2.33.BIN
- Date: 25 March, 2008

### Upgrade Instructions

8. Connect the computer to the LAN socket on the NP3680W.
9. Assign a static IP address to your computer in the range of 192.168.1.x.
10. Open the web browser (Internet Explorer, Mozilla Firefox, etc) on the computer, type in <http://192.168.1.100> on the address bar, and then press **Enter**.
11. Click **Maintenance**, and then click **Upgrade Firmware**.
12. Click **Choose File** to browse your computer for the firmware file. Once you have located the correct file, click **Open**, and then click **Upload**.
13. It will take a few minutes to upgrade the firmware. Do not turn off the modem during the upgrade.
14. The NP3680W will reboot itself after upgrade.

### New Features

- New feature: Supports Toshiba MFPs.

### Fixes:

- Fix bug: SMB protocol sometimes will run out of TCP/IP internal buffers.
- Fix bug: Cannot save file on Network Drive (SMB) using "Lotus SmartSuite" in Windows.
- Fix bug: Cannot see USB devices in Vista 64bit.

### Known Issues